

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1243**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1244**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1245**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1246**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1247**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1248**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1249**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1306**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences



Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1307**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1308**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1309**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1310**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1311**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1312**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1313**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1314**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences



Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1315**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1316**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1317**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1318**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1319**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1320**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1321**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1326**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences



Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1327**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1328**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences

Construction Sciences Pty Ltd  
ABN 74 128 806 735

5/06/2017

BMD Urban  
PO Box 197  
Wynnum  
QLD 4178

1 Fox Road  
Acacia Ridge QLD 4110  
Australia

PO Box 253  
Acacia Ridge QLD 4110  
Australia

Dear Sir

Phone: 61 7 3320 8500  
[www.constructionsciences.net](http://www.constructionsciences.net)

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL  
RIPLEY PROVIDENCE STAGE 32A – LOT NUMBER 1329**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



Geoff Turley  
Lab Manager  
For Brisbane South  
Construction Sciences