

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Cardno Construction Sciences Pty Ltd
ABN 74 128 806 735

1 Fox Road
Acacia Ridge QLD 4110
Australia

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.cardno.com.au

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 645**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Cardno Construction Sciences Pty Ltd
ABN 74 128 806 735

1 Fox Road
Acacia Ridge QLD 4110
Australia

PO Box 253
Acacia Ridge QLD 4110
Australia

Phone: 61 7 3320 8500
www.cardno.com.au

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 646**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 647**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 648**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 649**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 650**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 651**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 652**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 981**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 982**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 983**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 984**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 985**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 986**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 987**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 988**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 989**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 990**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 991**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 992**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 993**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 994**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 995**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 996**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 997**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 998**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 999**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1000**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1001**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1002**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1007**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1008**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1009**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1010**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1011**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1191**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1192**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1195**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au

Ref: 1979 P 1109

24th May 2016

BMD Urban Pty Ltd
PO Box 197
WYNNUM QLD 4078

Dear Sir

**INSPECTION OF PLACEMENT AND COMPACTION OF ALLOTMENT FILL
PROVIDENCE RIPLEY STAGE 20 – LOT 1196**

This is to confirm that placement and compaction of the allotment fill for the above project and Lot was supervised by Cardno Construction Sciences Pty Ltd under Level 1 arrangements as described in AS3798-2007 "Guidelines on earthworks for commercial and residential developments".

This indicates that the fill was compacted to at least the minimum density ratio in accordance with the specification requirements and it is considered that the fill may be deemed to be "controlled fill" in accordance with AS2870-2011 "Residential Slabs & Footings".

It may be that non-structural topsoil was placed on the block after completion of the structural fill. This would need to be removed as part of the site preparation for building and driveway construction.

I trust this meets your requirements. Please do not hesitate to contact me if you have any queries.

Yours faithfully



SANDY PAYNTER
LABORATORY MANAGER
For CARDNO
CONSTRUCTION SCIENCES DIVISION
alexander.paynter@cardno.com.au